



Set de inicio de baterías GBA 18 V 5.0 Ah AS

2 baterías de iones de litio con cargador rápido GAL 1880 CV. Tiempos de carga cortos gracias a la elevada corriente de carga de 8 amperios, la refrigeración de aire activa y la gestión de carga controlada por proceso. Fácil manejo y ahorro de espacio gracias al dispositivo para enrollar el cable de red. Para todos los equipos a batería con alojamiento para la batería AMPShare o Bosch Professional de 18 V. Tiempos de carga (80 % de la capacidad máx.): GBA 18 V 2.0 Ah: 15 min., GBA 18 V 4.0 Ah: 25 min., GBA 18 V 5.0 Ah: 35 min., ProCORE 18 V 4.0 Ah: 32 min., ProCORE 18 V 8.0 Ah: 68 min., ProCORE 18 V 12.0 Ah: 113 min.

252,98 € P.V.P. sin I.V.A.

N.º pedido: 9 26 04 246 01 0

Datos técnicos

DATOS GENERALES

Tensión

18 V

Capacidad

5 Ah

Adaptable para las siguientes máquinas

Taladro atornillador con acumulador

- > ASCM 18 QSW AS
- > ASCM 18-4 QM AS Set 5 Ah
- > ASCM 18 QSW AS Set 5 Ah
- > ASCM 18-4 QM AS Metal Advanced Top Set
- > ASB 18 Q AS Set 5 Ah
- > ABS 18 Q AS Set 5 Ah
- > ASCM 18-4 QM AS Universal-lean-top Set
- > ASCM 18-4 QM AS Set 5 Ah
- > ASCM 18-4 QMP AS
- > ASB 18 Q AS
- > ASCM 18-4 QM AS

- > ASCM 18-4 QM AS Metal
Advanced Set
- > ABS 18 Q AS

MULTIMASTER

- > Multimaster a batería
AMM 500 PLUS 4 Ah en
bolsa de nylon
- > Multimaster a batería
AMM 500 AS 2 Ah en
bolsa de nylon
- > MULTIMASTER a batería
AMM 700 Max AS 4 Ah
en bolsa de nylon
- > MULTIMASTER a batería
AMM 700 Max Top AS
- > MULTIMASTER a batería
AMM 700 Max AS
- > MULTIMASTER a batería
AMM 700 Max Top 4 Ah
AS
- > MULTIMASTER a batería
AMM 500 Plus AS
- > MULTIMASTER a batería
AMM 500 Plus Top AS
- > MULTIMASTER a batería
AMM 500 Plus Top 4 Ah
AS

Roedora

- > ABLK 18 1.6 E AS Set 2x
5 Ah
- > ABLK 18 1.6 E AS Set 1x
5 Ah
- > ABLK 18 1.6 E AS Set
1x 5 Ah
- > ABLK 18 1.3 CSE AS Set
2x 5 Ah
- > ABLK 18 1.3 CSE AS Set
- > ABLK 18 1.3 CSE AS Set
1x 5 Ah
- > ABLK 18 1.3 CSE AS Set
- > ABLK 18 1.3 CSE AS Set

Cizallas ranuradoras

- > ABSS 18 1.6 E AS Set 2x
5 Ah
- > ABSS 18 1.6 E AS Set 1x
5Ah
- > ABSS 18 1.6 E AS Set
- > ABSS 18 1.6 E AS

Cizallas para chapa



> ABL 18 1.6 E AS Set 1x
5 Ah

> ABL 18 1.6 E AS

> ABL 18 1.6 E AS Set 2x
5 Ah

Llave de impacto a batería

> ASCD 18-200 W4 AS Set
5 Ah

> ASCD 18-200 W4 AS

> ASCD 18-300 W2 AS

MULTIMASTER AUTOMOTIVE

> MULTIMASTER a batería
AMM 700 1.7 Q AS

> MULTIMASTER a batería
AMM 700 1.7 Q Autoglas

AS

Taladro percutor a batería

> ABH 18-26 AS Set 5 Ah

> ABH 18-26 AS

Saneamiento de juntas MultiMaster

> MULTIMASTER AMM 700
1.7 Q para el

saneamiento de juntas

Aspiradora en húmedo / seco

> ASBS 18-10 AS